


2.2 Coding Description



Options	
+3M	Quantity 2 SS316 pressure gauges on actuator side ports (OUT1, OUT2) Quantity 1 SS316 pressure gauges on supply port (IN)
+M20	Quantity 2 adapter for electrical connection M20x1,5
+Pack1	Software implementation with Valve Signature, Step Response, Pressure Fall Back
+TTL	Cable for high speed transfer data

NOTES:

- See section 3 "Technical Data" for Standard executions and more details.
- Special executions to be confirmed by IMI STI according to specific requirements.
- If +3M not required, quantity 3 pressure gauges SS304 always included.